

Order Number 6330-91-2421 / 1

Germany - Marketing - Holding

28 Nov 91 15:05 Page Number 1

Order Type Single Processor

Made On 27 Nov 91

Trigger Date 27 Nov 91 16:08

Priority STANDARD

OTC Receipt 27 Nov 91 PM

Request Ship Date 2 Dec 91

Comments Order created by EFO

Ship To NCR GMBH  
Germany - Marketing - Holding  
Gubenerstrasse 39  
D-8900 Augsburg  
Germany

Charge To NCR G.M.B.H  
Germany - Marketing - Holding  
P.O.Box 100090  
D-8900 Augsburg 1  
Germany

Customer BOEGL, Neumarkt  
System ITX MODEL35  
C.S.Id. 6330911581  
Reference 40466590  
Contract

Qty	Product Id.	Release	Description	Upd Media Set	Doc.
1	D902-3201-0000	07.00.40.	ITX Model 35, 9200 w/VAC SNA PU Type 2 Base	No S1, , , ,	1
1	D902-3205-0000	03.70.00.	ITX Model 35, 9200 w/VAC SNA/3270 DSC/LUS Printer	No S1, , , ,	1

Order Number 6330-92-0890 / 1

Germany - Marketing - Holding

29 Apr 92 10:08

Page Number 1

Order Type Single Processor

Made On 23 Apr 92

Trigger Date 23 Apr 92 22:56

Priority STANDARD

UTC Receipt 23 Apr 92 PM

Request Ship Date 28 Apr 92

Comments Order created by EFD

CSid 6330920890 created for order

Ship To NCR GMBH

Charge To NCR G.M.B.H

Customer BOEGL, Neumarkt

Germany - Marketing - Holding

Germany - Marketing - Holding

System ITX MODEL55

Gubenerstrasse 39

P.O.Box 100090

C.S.Id. 6330920890

D-8900 Augsburg

D-8900 Augsburg 1

Reference 40435910vora

Germany

Germany

Contract

Qty	Product Id.	Release	Description	Upd	Media Set	Doc.
1	A902-5000-0000	07.00.55.	ITX Model 55 Firmware	No	S1, , , ,	1
1	D902-0029-0000	03.03.00.	I-XPERT	No	F2, , , ,	1
1	D902-5001-006E	07.00.55.	ITX 9440, 94401P, Model 55 Operating System - German	No	S1, , , ,	1

MATRIX of A902-5000-0000 has been replaced by 07.00.55..

MATRIX of D902-5001-006E has been replaced by 07.00.55..

Add New Product by Dependency of D902-5001-006E/07.00.55..

Order Number 6330-92-1288 / 1

Germany - Marketing - Holding

18 Jun 92 15:06

Page Number 1

Order Type Single Processor

Made On 16 Jun 92

Trigger Date 17 Jun 92 09:05

Priority STANDARD

OTC Receipt 17 Jun 92 AM

Request Ship Date 19 Jun 92

Comments Order created by EFO

Ship To NCR GMBH

Charge To NCR G.M.B.H

Customer BOEGL, Neumarkt

Germany - Marketing - Holding

Germany - Marketing - Holding

System ITX MODEL55

Gubenerstrasse 39

P.O.Box 100090

C.S.Id. 6330920890

D-8900 Augsburg

D-8900 Augsburg 1

Reference 40495910vora

Germany

Germany

Contract

Qty	Product Id.	Release	Description	Upd Media Set	Doc.
1	A902-5500-0000	07.00.67.	ITX Model 55 Firmware	No S1, , , ,	1
1	D902-5001-006E	07.00.67.	ITX 94X0, 94X0IP, Model 55 Operating System - German	No S1, , , ,	1
1	D902-5201-0000	07.00.67.	ITX 94X0, 94X0IP, Model 55 SNA PU Type 2 Base	No S1, , , ,	1
1	D902-5205-0000	03.70.00.	ITX 94X0, 94X0IP, Model 55 SNA/3270 DSC/LUS Printer	No S1, , , ,	1
1	D902-5502-0000	07.00.67.	ITX 94X0, 94X0IP, Model 55 Native Cobol 85 Compiler	No S1, , , ,	1

MATRIX of A902-5500-0000 has been replaced by 07.00.67..

MATRIX of D902-5001-006E has been replaced by 07.00.67..

MATRIX of D902-5502-0000 has been replaced by 07.00.67..

MATRIX of D902-5201-0000 has been replaced by 07.00.67..

MATRIX of D902-5205-0000 has been replaced by LA.TE.ST..

LATEST release sucessfully replaced by 03.70.00.

# NCR 6091 SITE PREPARATION ERRATA SHEET

## CHANGED **KITS AND CABLES**

Page 10, Deleted Note 1, Terminator provided with 6091-2001, renumbered other notes.

Stacking kit	6091-K900-V001
Stability Base kit	6091-K901-V001
Host Connect Starter kit	6091-K911-V001 <sup>1</sup>
6091 to IBM Starter kit	6091-K910-V001
6091 Stack to 6091 Stack kit	6091-K905-V001
WORM media kit	6091-K300-V001
CD ROM Caddy	6091-K906-V001
Terminators	6091-K902-V001 Differential terminator 6091-K903-V001 Single-Ended terminator
External Cables <sup>3</sup>	1401-C522-00XX <sup>2</sup> Old style SCSI to new style connector 1401-C630-00XX High density to TOWER connector 1401-C631-00XX New style to high density connector 1415-C074-00XX High density to high density connector
<sup>1</sup> Contains cables, installation software, and single-ended termination. <sup>2</sup> The last two digits of the external cable number represent cable length in meters. Example: -0012 is 1.2 meters or 4 feet. <sup>3</sup> Refer to the "SCSI Connectors" and "Cable Types" sections for more information.	

## ADDED **SCSI ID THUMBWHEEL SWITCH** **IMPORTANT**

The SCSI ID must be unique for each device on a SCSI bus. If your NCR 6091 Subsystem is in a system with other SCSI devices, the SCSI ID thumbwheel switch on the back of the subsystem must be set to a SCSI ID that is different from any other SCSI ID on the SCSI bus.

NOTE: The SCSI ID for all 6091 *tape* devices in factory set at ID 3.

NOTE: The SCSI ID for all 6091 *disk* devices in factory set at ID 1.

In our constant quest for total Customer Satisfaction we are particularly concerned if you experience any problems with goods you receive from us. Please use this form to notify us if you have any problems with an order. Please note that the more accurate the form is completed the quicker the problem will be resolved. Gratis shipments will be performed if there is a problem due to an O.T.C. error.

O.T.C. FAX : (32)(2) 243 95 50

MAILplus : Ordering.6312@OTC

COUNTRY ORGANISATION :

ORDER NUMBER : .....-...-...../..

SOFTWARE GROUP :

MEDIA TYPE :

PRODUCT ID : .....-.....-.....

RELEASE : . . . . .

DESCRIPTION OF PROBLEM (Error messages, suspected causes, conclusion of analysis your organisation has performed)

- Order Problem : 0 Missing documentation  
                   0 Product missing/quantity on order incorrect  
                   0 Wrong product/release copied  
                   0 Media missing  
                   0 Incorrect invoice information

- Technical Problem : 0 Bad media (I/O errors)  
                       0 Wrong format/density/boot problem  
                       0 Customer caused problem

- Others :

COUNTRY ROOT CAUSE ANALYSIS RESULTS : \_\_\_\_\_

COUNTRY RECOMMENDED SOLUTION : \_\_\_\_\_

Do you require a re-shipment? If yes, please specify Product ID(s) and release(s)

.....-.....-..... . . . . .

.....-.....-..... . . . . .

Form prepared by :


Telephone :

Date :

N C R

SOFTWARE-VERTEILUNG

SEPT 1990



Sehr geehrte Damen und Herren,

falls Sie die von uns gelieferten Betriebssystem-Software selbst installieren, und dabei auf Probleme stoßen, wenden Sie sich bitte an das Software-Service-Zentrum Augsburg,

**T e l e f o n : 0821/405-8500.**

Von dort wird Ihr Problem an das zuständige Produkt-Kompetenz-Zentrum weitergeleitet.

Dieser Bereich wird sich um Ihr Problem kümmern.